

BUREAU OF ENVIRONMENTAL REMEDIATION

SUBJECT
Marco Site, Chanute

Bill called to inform me that some kids were playing around the B.S. pit and one fell in over this weekend. He was apparently covered with the sludge but is okay now.

Bill walked through the site today and observed almost all of the buildings were accessible. There were many containers spread throughout the site and inside buildings-marked and unmarked. He observed marked containers of TCE, toluene, mercury, and cylinders of Nitrogen; Asbestos was observed throughout the site.

Contact site owners. Visit site and take a general inventory. Possibly initiate EPA immediate removal action.

Left message for main site owner & two other major site PRPs including MFA Oil. The current B.S. pit site owner was not listed in the phone directory. I will visit the site this Friday, October 9, 1992.

cc: Pat Casey, Legal
Greg Crawford, Public Information
Bill Thornton, SEDO

Mid-America Ref.
KSO 084091545
1-1
10-6-92
07 KN



SUPERFUND RECORDS